CERTIFIED LAND CORNER RESTORATION

Index No. C-18

37090220 30

State of Wisconsin } ss.
County of Oneida

I Philip T. Hansen, do hereby certify that on the 4th day of October, 19 75, I found evidence of the N.E. 1/16 corner of Section 2, Township 37, North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:

Jim H Flin

Hans Kocher

WISCONSIN PHILIP T. HANSEN S-233 LAND SURVEYOR

T37N R9E



○ = Corner monument restored.

History of original corner establishment:

Corner established by R. Loftus, Adpco Surveyor.

Description of corner evidence found:

Recovered 3/4" I.P. iron pipe with brass cap, [illegible]. Monument projects 4" above ground. Recovered in good condition. [illegible] recovered.

N.E. 1/16

Description of monument and accessories I established to perpetuate the original location of this corner.

As monument was recovered in good condition and firmly set in ground, it was left in place. Added [illegible] 1/4 to brass cap.
NITS - Red Pine 3" [illegible] 107.0 links, scribed 1/16 SE.
Red Pine 3" [illegible] 157.1 links, scribed 1/16 SE.

Dated at Rhinelander, Wis., this 3rd day of November, 19 76

Signature Philip T. Hansen Title Registered Land Surveyor Registration No. S-498
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida, I hereby certify that the within instrument was filed in this office for record on the 16th day of November, 19 76 at 2:00 o'clock P M.

Doris Verage Kucha
(Register of Deeds)

By ..... Deputy

FORM 985 H. C. MILLER CO., MILWAUKEE