

State of Wisconsin }
 County of Oneida } ss.

CERTIFIED LAND CORNER RESTORATION

Index No. **D-17**


I Phillip M. Tansen, do hereby
 certify that on the 22nd day
 of September, 1976, I found

evidence of the 1/16
 corner of Section 2, T. 3
 Township 37, North, Range
9 East, Fourth Principal Meridian,


as described hereon; and that from this evidence
 I established a new monument and accessories
 as described hereon to perpetuate the original
 location of this corner.

Resident witnesses:

Jim Steffen
Tom Wagner



T37N 19E



○ = Corner monument restored.

History of original corner establishment:

Corner established by H. Loftus, Alpo surveyor, in 1958.

Description of corner evidence found:
 Recovered 3/4" Iron pipe with 3" x 2" brass cap 25 links east of two welded
1/2" reinforcement rods set in the pavement of old Highway 17 (centerline).
 Brass cap stamped:

Cor. 25 links
 East
 1/16 22/24
 Alpo

Description of monument and accessories I established to perpetuate the original location of this corner.
 As the witness monument and corner were in good condition, it was left in place.
 Witness corner rejects 1 1/2" above ground.
 W.P. - Slack of race 6" x 35' ... 00.9 links, secured 1/16 W.P.
Marked 3" x 37' ... 72.8 links, secured 1/16 W.P.
 Bearings and distances made to true corner.

Dated at Oneida, Wis., this 3rd day of November, 1976

Signature: Phillip M. Tansen Title: Registered Land Surveyor Registration No. 498
 County Surveyor, Registered Land Surveyor or other duly authorized official

Office of Register of Deeds, County of Oneida
 Instrument was filed in this office for record on the 16th day of November, 1976
 at 2:05 o'clock P. M.

Lois Leverage Fisher
 (Register of Deeds)

By: _____ Deputy

3709031000