

CERTIFIED LAND CORNER RESTORATION

Index No. P-12


History of original corner establishment:  
Corner recovered by N. Loftus, Ripco Surveyor. Set iron pipe with brass cap.  
No reference made to ETs marked.

State of Wisconsin } ss.  
County of Oneida

I, Phillip T. Hansen, do hereby certify that on the 26th day of August, 1977, I found evidence of the EC 1/16 corner of Section 21 Township 37 North, Range 9 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner.

Resident witnesses:  
Jim Clafflin  
Terb Kozmer  
PHILIP T. HANSEN  
ARGONNE, WIS.  
S-498  
WISCONSIN LAND SURVEYOR

T37N R9E



○ = Corner monument restored.

Description of corner evidence found:

Recovered 3/4" iron pipe with 2" brass cap, not stamped.  
Pipe was loose in ground.  
Recovered CBTs - Maple 7" S16, 27.1 lbs, scribbing grown over.  
Maple 5" S70, 17.8 lbs, scribbing partially legible.

Description of monument and accessories I established to perpetuate the original location of this corner.  
Reset iron pipe and placed rock cairn around base.  
Monument projects 20" above ground. Stamped cap:  
T37N R9E

EC 1/16 + S21

Dated at Rhineland, Wis., this 9th day of September, 1977.

Signature Phillip T. Hansen Title Registered Land Surveyor Registration No. S-498  
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida  
Instrument was filed in this office for record on the 15th day of September, 1977  
at 2:00 o'clock P.M.

Thomas Wenzel  
(Register of Deeds)

By: \_\_\_\_\_ Deputy

3709212010