

CERTIFIED LAND CORNER RESTORATION


Index No. R-20

State of Wisconsin } ss.
County of Oneida

History of original corner establishment:
Corner established by N. Loftus, Ripco surveyor, in 1956.
Recovered old post with fence lines running south and west.
Set a 3/4" iron pipe with 2" brass cap.

I Phillip T. Hansen, do hereby
certify that on the 9th day
of June, 1980, I found
evidence of the E 1/16
corner of Sections 23, 26
Township 37, North, Range
9 East, Fourth Principal Meridian,
as described hereon; and that from this evidence
I established a new monument and accessories
as described hereon to perpetuate the original
location of this corner.

Resident witnesses:
J. Clafflin
H. Wagoner




Description of corner evidence found:

- Recovered 3/4" iron pipe with 2" brass cap, stamped: S23
- Monument projects 18" above ground.
- Recovered old BT's - E 1/16
- Balsam 7" S47°E 7.4 links, S26
- now dead - scribed E 1/16 BT.
- Balsam 3" N49°E 12.00 links, RIPCO
- now dead - scribed E 1/16 BT.

Description of monument and accessories I established to perpetuate the original location of this corner.

- Monument left as recovered.
- Marked NBT's -
- Maple 7" S55°E 29.4 links
- Maple 4" N72°W 43.8 links
- scribed 1/16 BT.



○ = Corner monument restored.

Dated at Rhineland, Wis., this 22nd day of July, 1980

Signature: Phillip T. Hansen Title: Registered Land Surveyor Registration No. S-498
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida, I hereby certify that the within
instrument was filed in this office for record on the 30th day of July, 1980
at 10:15 o'clock A. M.

Signature: David George Fiedler
(Register of Deeds)

By: _____ Deputy

3709230010