


CERTIFIED LAND CORNER RESTORATION

Index No. H-6

State of Wisconsin } ss.  
County of Oneida

History of original corner establishment:  
Corner established by N. Loftus, Ripco surveyor, in 1954.  
Set SW 1/16 corner at 20.21 chains from W 1/16 between sections 8 and 17.

I, Philip T. Hansen, do hereby certify that on the 12th day of May, 1980, I found evidence of the SW 1/16 corner of Section 8 Township 37 North, Range 10 East, Fourth Principal Meridian, as described hereon; and that from this evidence I established a new monument and accessories as described hereon to perpetuate the original location of this corner




Resident witnesses:  
Jim Claflin  
Herb Wagoner

Description of corner evidence found:

Recovered 3/4" iron pipe with 2" brass cap, stamped:  
Monument projects 12" above ground.  
Recovered OBT.  
Black Spruce 12" S30°E 35.2 links  
Cut into tree. Scribe marks apparent.  
Don't believe this to be one of Ripco BT's.  
SW 1/16 S 18  
RIPCO

Description of monument and accessories I established to perpetuate the original location of this corner.  
Monument left as recovered.  
Marked NBT -  
R. Pine 7" S19°W 99.7 links  
scribed 1/16 BT.



○ = Corner monument restored.

Dated at Rhineland, Wis., this 21st day of July, 1980

Signature: *Philip T. Hansen*  
County Surveyor, Registered Land Surveyor, or other duly authorized official) Title: Registered Land Surveyor Registration No. S-498

Office of Register of Deeds, County of Oneida  
Instrument was filed in this office for record on the 21st day of July, 1980 at 3:35 o'clock P.M.

*Doris Waage Fuchs*  
(Register of Deeds)

By: \_\_\_\_\_ Deputy