

CERTIFIED LAND CORNER RESTORATION

Index No. Y-3

State of Wisconsin

County of Oneida

} ss.

I Phillip T. Hansen, do hereby

certify that on the 16th day

of March, 1978, I found

evidence of the SC 1/16

corner of Section 31

Township 38, North, Range

10 East, Fourth Principal Meridian,


as described hereon; and that from this evidence

I established a new monument and accessories

as described hereon to perpetuate the original

location of this corner.

T38N R10E



Description of corner evidence found:
Recovered a 3/4" iron pipe with alloy cap, stamped:
Pipe projects 16" above ground.
Recovered OBT's -
White Pine 14" S62°W, 23 links
scribed CS 1/16 31 BT
Black Spruce 8" N32°W, 16.2 links
scribed CS 1/16 31 BT

S 31
CS 1/16
T38N R10E

Description of monument and accessories I established to perpetuate the original location of this corner.
No additional accessories established.


Dated at Rhineland, Wis., this 18th day of May, 1978.

Signature Phillip T. Hansen Title Registered Land Surveyor Registration No. S-498
(County Surveyor, Registered Land Surveyor, or other duly authorized official)

Office of Register of Deeds, County of Oneida
Instrument was filed in this office for record on the 22nd day of May, 1978
at 10 o'clock P M.

Dora George Fisher
(Register of Deeds)

By: _____ Deputy



○ = Corner monument restored.